



## AC-Check



### Non-contact voltage tester with adjustable sensitivity

Rev.1213



- **Contactless detection** of live lines from 5 V AC to 1000 V AC
- **Locates electrical voltages** in cables, sockets, bulb sockets and fuses
- **Determines polarity of L/N conductors**, e.g. on sockets or terminals
- **Finds breaks** in wires and cables
- **CAT III - 1000 V** – can be used for measurements throughout building installations
- **Extremely high sensitivity** for tracing lines at great depths
- **Clearly visible LED** for signalling electrical voltages
- **Super-bright, integrated flashlight** with separate ON/OFF button
- Rugged, impact-resistant **quality enclosure**

#### TECHNICAL DATA

**INDICATOR LED**, Acoustic signal

**VOLTAGE RANGE**  
5 V/AC ... 1000 V/AC  
Frequency 50 ... 400 Hz

**OVERVOLTAGE CATEGORY**  
CAT III - 1000V

**POWER SUPPLY**  
2 x AAA 1.5 V alkaline batteries

**OPERATING TEMPERATURE**  
0 °C ... 40 °C

**DIMENSIONS (W x H x D)**  
154 x 32 x 28 mm

**WEIGHT (incl. batteries)**  
50 g



Adjustable sensitivity

Flashlight



**AC-Check**  
+ batteries (2 x 1.5 AAA)

**Packing dimension (W x H x D)**  
-

ARTICLE	ARTICLE NO	EAN-CODE	PU
AC-Check	083.008A	4 021563 687862	5

